DUT63734

1967 DEC 4 23 52 Z

25X1

P Ø42341Z DEC 67 FM NPIC WASHDC TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA RUCVAAA/2D RTS BARKSDALE AFB LA RUEPJS/DIA WASHDC RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUCVAAA/2 AF BARKSDALE AFB LA RUEFHOA/HOS USAF/AFRDR INFO RUEPIA/CIA WASHDC BT

SECRET CITE NPIC 2390. 15TH AF (FOR DI). SAC (GLASS LAMP/DOCR, DM 4) 2D AF (FOR DI). AFRDR (ATTN:

1. CAMERA B-24 WAS USED ON MISSION G 998 FLOWN 1 DECEMBER 1967. PROCESSING WAS ACCOMPLISHED BY NAV PECON TECH SUPPCEN.

A. EXPOSURE AND RESOLUTION ARE GOOD.

OR SIDE: THE POSITION INDICATOR IMAGES APPEAR UNDER-EXPOSED THROUGHOUT. MINUS DENSITY DOTS ARE PRESENT IN THE FIRST FEW FRAMES OF THE MISSION. PLUS DENSITY AREAS APPROXIMATELY 0.5 INCH IN DIAMETER ARE PRESENT OCCASIONALLY NEAR THE DATA BLOCK CORNER OF THE FORMAT. FAINT PLUS DENSITY AREAS ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE THROUGHOUT. FRAMES 1432, 1472, 1478, AND 1491 HAVE ROLLER CINCH MARKS ACROSS THE MINOR AXIS OF THE FILM. FRAME 828 CONTAINS A HEAT SPLICE AND FRAME 306 CONTAINS A MANUFACTURER'S SPLICE.

C. 9L SIDE: FAINT PLUS DENSITY AREAS ASSOCIATED WITH ROLLER CHATTER APPEAR INTERMITTENTLY ALONG THE INBOARD EDGE. FRAME 639 CONTAINS A MANUFACTURER'S SPLICE; FRAME 861 CONTAINS A HEAT SPLICE; FRAMES 950 AND 951 HAVE A HEAT SPLICE BETWEEN THEM. APPROXIMATELY 25 PERCENT OF FRAME 873 HAD BEEN DAMAGED AND REPAIRED. FRAMES 601-900 ARE TITLED INCORRECTLY (301-600).

D. BOTH SIDES: MINOR EDGE STATIC IS PRESENT ALONG THE OUTBOARD EDGES OF THE FIRST 900 FRAMES. MODE FIVE WAS USED THROUGHOUT WITH A CYCLE RATE OF 4.5 SECONDS. THE LAST TITLED FRAME IS 1491.

3. POSITIVE:

A. PRINTING AND PROCESSING ARE GOOD. B. PI SUITABILITY IS FAID TO COORD.

PI SUITABILITY IS FAIR TO GOOD.

CLOUDS OBSCURE APPROXIMATELY 35 PERCENT OF THE MISSION.

GP - 1

SECRET

END OF MESSAGE



Experience of A SECTION AND A SECTION C.R. S. L. S. S. S.

Declassification Review by NGA/DoD